General Environmental Incident Summary

Incident: 5678 **Notice:** 4/16/2018 0150 **Occurred:** 4/16/2018 0945

DEM Incident No: No Further Action:

Responsible Party: Lama Trucking, Inc.

County: Burleigh
Twp Rng Sec Qtr: 138 80 11

Lat Long + Method: 46.79116 -100.74780 Interpolation from map

Location Description: South side of Sam's Club Parking Lot, 2821 21 Rock Island Place,

Bismarck, ND 58504

Submitted By Info: Lance Loken

WPC, Inc.

1102 South Washington Street

Suite 210

Bismarck ND 58504

Received By Info:

Contact Info:

140 S. Pinnacle Drive

Romeoville IL 60446

Affected Medium: 09 - other Near. Occupied Bldg: 0.5 Miles

Type of Incident: Leaking Drum in Tractor Trailer

Release Contained: Yes
Reported to NRC: Unknown

Contaminant: 10/40 Motor Oil
Volume of Release: 55 gallons

Duration of Release:

Agriculture Related: No

EPA Extremely

Hazardous Substance: NoNumber of Fatalities: 0Number of Injuries: 0

Cause of Incident:

Loading mishap punctured a 55-gallon drum in the trailer. Discovered when they came to unload the semi in Bismarck, ND.

Risk Evaluation:

Spill contained mostly in the tractor-trailer. Floor dry and booms are down to control any runoff. Exterior is on asphalt parking lot.

Potential Env. Impacts:

None at this time.

Action Taken/Planned:

Western Plains Consulting has been contacted to contain, clean-up and arrange for disposal of waste.

Wastes Disposal Location:

Bismarck Municipal Waste Facility.

Other Agencies Involved:

Updates

Date: 4/16/2018 Status: Reviewed - Follow-up Required

Author: Stockdill, Scott

Notes:

According to the incident summary, this incident involved an uncontrolled release. Follow-up is

necessary.

Updated Volume: None at the time of this update

Date: 4/16/2018 Status: Inspection

Author: Schmitt, Bryan

Notes:

Date: 4/16/2018 Time: 15:15 CST

Motor oil was leaking out of the cargo trailer onto the tires and pavement. Western Plains Consulting, Inc. (WPC) was on site removing contaminated pallets and containing the spill. WPC was laying down absorbent around the truck and isolating the contaminated area. No impacts to storm or sanitary sewer were observed. The spill appeared to be on pavement and no vegetation was impacted.

Updated Volume: None at the time of this update